

100 Psi Absolute Pressure Sensor

PS-100A-OEM-LD05

Calibration



0 Psi A = 0.500 v

100 Psi A = 4.500 v

1/8npt Thread, 17mm Hex


Connector Kit

CON-KIT-TI-LZ06



Wiring looking into sensor

PIN	Description
A	0 V
B	5 V
C	Signal



Push wire through connector
Crimp on terminal
Pull wire / terminal back into connector