

150 Psi Gauge Pressure Sensor

PS-150G-OEM-LD05

Calibration



0 Psi G = 0.500 v

150 Psi G = 4.500 v

1/8npt Thread, 17mm Hex


Connector Kit

CON-KIT-TI-LZ06



Wiring looking into sensor

| PIN | Description |
|-----|-------------|
| A | 0 V |
| B | 5 V |
| C | Signal |



Push wire through connector
Crimp on terminal
Pull wire / terminal back into connector