

# 150 Psi Gauge Pressure Sensor

PS-150G-OEM-LD05

## Calibration



0 Psi G = 0.500 v

150 Psi G = 4.500 v

1/8npt Thread, 17mm Hex


Connector Kit

CON-KIT-TI-LZ06



## Wiring looking into sensor

PIN	Description
A	0 V
B	5 V
C	Signal



Push wire through connector  
Crimp on terminal  
Pull wire / terminal back into connector